

## Issue: CoxBox Core/GPS will not fit in the current cup holder.



When pressing the CoxBox into the cup holder, it is creating an airtight seal and the result is this air pressure is not allowing the CoxBox to sit at the bottom of the cup.



To correct this, you can simply drill a small hole in the bottom of the cup to allow the air to escape and the CoxBox should then be able to fit in the cup. This obviously shouldn't be done if the cup is mounted in the bulkhead. We will look to fix this with a new revision of the cup holder in the future.